

Certificate of Compliance

Certificate Number:

R38679

Report Reference:

R38679-2018-11-27

Issue Date:

2024-02-21

Issued to:

Coopers Fire Ltd

Ignis House, Houghton Ave

Hants

Waterlooville, PO7 3DU United Kingdom

This certificate confirms that representative samples of:

Fire-protective Curtains

FireMaster Concertina, FireMaster Concertina Egress,

FireMaster Egress and FireMaster Non-Egress.

Has been evaluated by UL LLC in accordance with Standard(s) for Safety:

UL 10D, Fire Tests of Fire-Protective Curtain Assemblies, Edition 2

Additional Information:

See UL Product iQ® at <https://ig.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch

UL Mark Certification Program Owner

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.



Certificate of Compliance

Certificate Number: R38679
Report Reference: R38679-2018-11-27
Issue Date: 2024-02-21

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Fire-protective curtain, Model FireMaster Concertina, 4 hr fire rating.

Fire-protective curtain, Model FireMaster Concertina Egress, 2 hr fire rating (EFP A1 Fabric with or without vision panel EFPTM 2/1000/VP)

Fire-protective curtain, Model FireMaster Egress, 3 hr fire rating (when installed into gypsum/plaster board walls), 4 hr when installed into masonry walls (EFP A1 Fabric with or without vision panel EFPTM 2/1000/VP)

Fire-protective curtain, Model FireMaster Non-Egress, 3 hr fire rating when installed into gypsum/plaster board walls), 4 hr when installed into masonry walls (EFP A1 Fabric with or without vision panel EFPTM 2/1000/VP).